



## RECORD OF MEETING

|   |   |
|---|---|
| <p><b>PURPOSE OF MEETING:</b></p> <p>Albion Park Quarry – Community Consultative Committee Meeting</p>  | <p><b>MEETING NUMBER:</b></p> <p>APQ-CCC-07</p> <p><b>MEETING DATE:</b></p> <p>19 July 2013</p> <p><b>VENUE:</b></p> <p>Albion Park RSL</p> |
| <p><b>ATTENDEES:</b></p> <p>Brian Weir [chairperson] (BW), Susan Dunster (SD), John Murray (JM), Steven Crandell (SC)<br/>Arthur Webster (AW)</p> <p><b>APOLOGIES:</b></p> <p>None</p> <p>No representative from Shellharbour City Council attended</p> | <p><b>DISTRIBUTION:</b></p> <p>All Attendees &amp; Apologies</p> <p>Director-General, Department of Planning</p>                            |

Items are given the meeting number first and then an item number, then each item will have an individual number to be carried forward with it if raised again at future meetings.

| ITEM | DATE RAISED | DESCRIPTION  | STATUS COMPLETE/IN PROGRESS | ACTION BY WHOM | ACTION BY WHEN |
|------|-------------|--|-----------------------------|----------------|----------------|
|      |             | <p>Meeting commenced at 10:00am</p> <p>AW advised that Brian Weir had been appointed as Chairperson for this CCC by the DoPI.</p>  |                             |                |                |
| 1    |             | <p><b>Review of Previous Minutes</b></p> <p>Minutes from previous meeting on 15 February 2013 accepted as correct.</p>   |                             |                |                |
| 2    |             | <p><b>Current Works</b></p> <p>(S.C.)advised that the quarry production was:</p> <p style="padding-left: 40px;">Dec./March 156,000 tonnes</p> <p style="padding-left: 40px;">April/June 143,000 tonnes</p> <p>The major projects during this period were Enfield &amp; Princes Hwy, Gerringong. The Enfield project is nearing completion which will reduce quarry production over the next period.</p> <p>All blasting levels have been within allowable limits. A new contractor has been engaged to improve blasting performance.</p> |                             |                |                |

| ITEM      | DATE RAISED | DESCRIPTION  | STATUS COMPLETE/IN PROGRESS | ACTION BY WHOM | ACTION BY WHEN |
|-----------|-------------|--|-----------------------------|----------------|----------------|
| 2<br>cont |             | <p>A contractor is currently working on weed control and will begin a planting program in spring in accordance with the approved rehabilitation program. Further work will be carried out to repair plants damaged by feral goats.</p> <p><b>Questions</b><br/>S.D asked if Holcim uses the same blast monitor as Cleary Bros. SC will check and advise. SC advised that prior to each blast, the manager logs on to the monitor to view the blast results which are also sent through to their blasting consultant. Prior to each blast the consultant must approve the drilling pattern &amp; loading details to ensure that the environmental consent conditions will be met.</p> <p>Note It has been confirmed post meeting that Holcim do not use the same blast monitor as Cleary Bros. Their blast monitor is at a different location.</p>                                  |                             |                |                |
| 3         |             | <p><b>Environmental Monitoring Results</b><br/>AW advised the following:<br/>The Annual AEMR is currently being prepared and will be distributed at the end of August.</p> <p>Dust Gauge 1 is located adjacent to the front access gate on the East West Link and is continuing to be an unreliable location as the results are being affected by other sources. The other 3 gauges are recording levels well within the required limits. The EPA has recommended that the gauge be relocated to a more reliable location.</p> <p>One (1) complaint was received in March 2013 relating to a blast. The blast noise and vibration on this date was well below EPA and Consent limits.</p> <p>Monthly flow measurements recommenced on Watercourse 1 and 2 in May 2013 using a handheld probe by ALS Laboratory to replace the automated loggers that were not performing well.</p> |                             |                |                |

| ITEM      | DATE RAISED | DESCRIPTION   | STATUS COMPLETE/IN PROGRESS | ACTION BY WHOM | ACTION BY WHEN |
|-----------|-------------|---|-----------------------------|----------------|----------------|
| 3<br>cont |             | <p>The results for the bi-annual boreholes in June 2013 showed no anomalies to historical data.</p> <p>Weed control is continuing in the revegetation area and planting in Section 3 is currently programmed to occur in Spring 2013 when the weather conditions are more favourable.</p> <p><b>Questions:</b><br/>In regard to blasting frequency S.C advised that during the recent high production demand, blasting occurred up to three times per month. He expects this to be about two to three blasts per month in the future.</p>   |                             |                |                |
| 4         |             | <p><b>Other Business</b></p> <p>JM asked where the rehabilitation areas are. An aerial photo was tabled and SC identified areas which are essentially south of the quarry area and also on the mound to the north east. AW commented that feral goats have been a big problem in destroying parts of the rehabilitation work.</p> <p>.</p> <p>SD noted that there was no representative from Shellharbour City Council at this meeting and was disappointed that she was still seeking advice from Shellharbour City Council (SCC) if they had been informed about the approval to increase production from 400,000 ton to 600,000 ton and what was their response to this increase. As there was no SCC representative in attendance, it is requested that the SCC representative respond to this question at the next CCC meeting</p> <p>.</p> <p>The next meeting will be scheduled in November at a date to be confirmed.</p> |                             | SCC rep        | next meeting   |
| 5         |             | <p><b>Meeting Conclusion</b></p> <p>There being no further business, the meeting closed at 10:35am.</p>   |                             |                |                |