Record of the Site Inspection Cleary Bros Albion Park Quarry Community Consultative Committee Held at Cleary Bros Albion Park Quarry, Croom Tuesday 17 December 2019 at 9:00 am

Present:

Chairperson Brian Weir (BW)

Fig Tree Hill Representative Susan Dunster (SD)

Shellharbour City Council Representative Mark Miller (MM)

Cleary Bros Environmental Officer Mark Hammond (MH)
Cleary Bros Representative Todd Kalajzich (TK)

Apologies:

Community Representative John Murray (JM)

Item 1: Site Inspection

All representatives except for TK met at the weighbridge where they were transported through the Sales Area where representatives were able to observe the produced material stockpiles and main crushing plant which was in operation at the time of the visit.

Representatives except for TK were then transported into the "Pit 2" area of the quarry to the processing plant which is used primarily to manufacture roadbase, and which was not operating at the time of the inspection.

Representatives except for TK then observed site operations in the active pit (Pit 3), which included a prepared drill pattern that is planned to be fired on Thursday, loading and hauling of rock from blasted parts of the site with an excavator and trucks, a mobile crusher in operation, water cart undertaking dust suppression, and a dozer and grader regrading overburden on an area to be rehabilitated.

All representatives then observed part of the Stage 7 area proposed for future extraction from the top of the acoustic bund, which provided a vantage offsite in all directions, as well as views of the current quarry and adjacent quarry operations.

All representatives then travelled back to the weighbridge where the site inspection was concluded.

Throughout the site inspection there was considerable discussion of site activities and the extraction process, forthcoming works, and future developments. There were no matters outstanding at the end of the site inspection.

Site visit completed 10:00 am

