

Complaint Register

Division:		Quarry		Location:		Albion Park Quarry	
No.	Date Raised	Summary of Complaint	Summary of Action (if any)	Agreed Completion Date	Date of Verification Close Out		
QC105	20/9/2018	Complaint received via EPA Environmental Line regarding visible dust over the Albion Park Quarry at 9:40am on the 17/9/2018	Localised dust plume related to rupture of dust filter on main processing plant. Dust filters have now been replaced. Weather conditions at the time were a light ENE breeze, with no impacts to external receptors.	24/9/2018	24/9/2018		
QC106	1/3/2019	Vibration from blast 03/19 was worse than usual.	Nil action required – Noise and vibration levels within approved limits.	4/3/2019	4/3/2019		
QC107	21/6/2019	Noise from blast 13/19 was loud	Nil action required – Noise from blast was within approved limits.	21/6/2019	21/6/2019		